



COVERING MATERIALS

STINSON RELIANT V-77 & V-78

SYSTEM VI

Quantity		Part Number	Description
78	Yd.	SF102	2.7 oz. Certified Fabric
3	Gal.	U500-01	Urethane Adhesive
4	Gal.	SF-MEK	Methyl Ethyl Ketone
4	Gal.	Superwash	Fabric Cleaner
1	Roll	SF102-1P	1" Pinked Edge Surface Tape
11	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF102-3PB	3" Pinked Edge Bias Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
5	Roll	SF-REINF 3/8"	3/8" Reinforcement/Anti Chafe Tape
50	Ea	09-19200	Inspection Rings
25	Ea	09-19300	Inspection Plates
2	Pkg	L274	Drain Grommets
2	Roll	SF694-500	Flat Rib Lacing Cord
2	Ea	504-20	20" Straight Rib Stitching Needle
1	Gal.	SF10-01	Epoxy Metal Primer
2	Qt.	SF320-04	Epoxy Metal Primer Catalyst
5	Gal.	SF6500-01	Fabric Primer Base
40	Pt.	SF6600-08	Fabric Primer Catalyst
20	Pt.	SF6700-08	Fabric Primer Flex Agent
5	Gal.	SF6820-01	Primer & Paint Reducer
8	Gal.	Superthane	System VI Urethane Topcoat
16	Pt.	SF6950-08	Topcoat Catalyst

optional materials:

[Pre-shrunk Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Viscosity Cups](#)
[Paint Strainer Cones](#)
[Tyvek Paint Suit](#)
[D-102 System VI Covering Manual](#)