



## COVERING MATERIALS

### AVIAT HUSKY

#### SYSTEM I

Quantity		Part Number	Description
45	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
2	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
30	Ea.	09-19200	Inspection Rings
15	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
1	Gal.	SF10-01	Epoxy Metal Primer
2	Qt.	SF320-04	Epoxy Metal Primer Catalyst
1	Gal.	Superthane	Urethane Topcoat for Metal
2	Pt.	SF6950-08	Urethane Topcoat Catalyst
1	5Gal	300-5	Dacproofer
1	5Gal	132-5	Retarding Thinner
2	5Gal	125-5	Clear Butyrate
2	5Gal	131-5	Thinner
2	5Gal	301-5	SpraFil
2	5Gal	131-5	Thinner
10	Gal	Tinted Butyrate	Butyrate Topcoat
1	5Gal	132-5	Retarding Thinner

#### optional materials:

Pre-shrunk Fabric tapes  
KA25B25 Gluemaster Glue Gun  
Coverite Iron  
Calibrating thermometers  
Invisible Gloves  
Rib Stitching Needles  
Paint Strainer Cones  
Round Rib Lacing Cord  
C-102A System I Covering Manual