



COVERING MATERIALS

KOLB FIRESTAR & KOLB EXTRA

SYSTEM I

Quantity		Part Number	Description
28	Yd.	SF104A	1.7 oz Lightweight Fabric
3	Qt.	U500-04	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
1	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF694-500	Flat Rib Lacing Cord
1	Roll	SF-REINF 3/8"	3/8" Anti Chafe/Reinforcement Tape
1	Pkg	L274	Drain Grommets
2	Qt.	SF10-04	Epoxy Metal Primer
1	Qt.	SF320-04	Epoxy Metal Primer Catalyst
1	Qt.	Superthane	Superflite Urethane Metal Topcoat
1	Pt	SF6950-08	Superthane Catalyst
3	Gal	300-1	Dacproofer
3	Gal	132-1	Retarding Thinner
1	5Gal	125-5	Clear Butyrate
1	Gal	125-1	Clear Butyrate
1	5Gal.	131-5	Thinner
1	Gal	131-1	Thinner
1	5Gal	301-5	SpraFil
1	5Gal	131-5	Thinner
8	Gal	Tinted Butyrate	Butyrate Topcoat
4	Gal	132-1	Retarding Thinner

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Rib Stitching Needles
Paint Strainer Cones
Round Rib Lacing Cord
C-102A System I Covering Manual