



COVERING MATERIALS

FOKKER D-VII, JENNY

SYSTEM I

Quantity		Part Number	Description
55	Yd.	SF104A	1.7 oz Lightweight Fabric
1	Gal	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
4	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
16	Ea	09-19200	Inspection Rings
16	Ea	09-19300	Inspection Plates
1	Pkg	L274	Drain Grommets
7	Pkg	AD42ABS-LF	Pop Rivets (100 per pack)
1	5Gal	300-5	Dacproofer
1	Gal	300-1	Dacproofer
1	5Gal	132-5	Retarding Thinner
1	Gal	132-1	Retarding Thinner
2	5Gal	125-5	Clear Butyrate
2	5Gal	131-5	Thinner
2	5Gal	301-5	SpraFil
2	5Gal	131-5	Thinner
14	Gal	Tinted Butyrate	Butyrate Topcoat
1	5Gal	132-5	Retarding Thinner
2	Gal	132-1	Retarding Thinner

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Rib Stitching Needles
Paint Strainer Cones
Round Rib Lacing Cord
C-102A System I Covering Manual