



COVERING MATERIALS

RANS S-6S

SYSTEM I

Quantity		Part Number	Description
32	Yd.	SF102	2.7 oz Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
1	5Gal.	300-5	Dacproofer
4	Gal	300-1	Dacproofer
1	5Gal	132-5	Retarding Thinner
4	Gal	132-1	Retarding Thinner
2	5Gal	125-5	Clear Butyrate
2	5Gal	131-5	Thinner
2	5Gal	301-5	SpraFil
2	5Gal	131-5	Thinner
10	Gal	Tinted Butyrate	Butyrate Topcoat
1	5Gal	132-5	Retarding Thinner

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Rib Stitching Needles
Paint Strainer Cones
Round Rib Lacing Cord
C-102A System I Covering Manual