



## COVERING MATERIALS

### RANS S-9 & S-10

#### SYSTEM I

Quantity		Part Number	Description
32	Yd.	SF102	2.7 oz Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
2	Rolls	SF-REINF 1/2"	1/2" Anti Chafe/Reinforcement Tape
30	Ea	09-19200	Inspection Rings
15	Ea	09-19300	Inspection Plates
1	Pkg	L274	Drain Grommets
1	Roll	SF694-500	Flat Rib Lacing Cord
3	Gal	300-1	Dacproofer
3	Gal	132-1	Retarding Thinner
1	5Gal	125-5	Clear Butyrate
1	5Gal	131-5	Thinner
1	5Gal	301-5	SpraFil
1	5Gal	131-5	Thinner
9	Gal	Tinted Butyrate	Butyrate Topcoat
1	5Gal	132-5	Retarding Thinner

#### optional materials:

[Pre-shrunk Fabric tapes](#)  
[KA25B25 Gluemaster Glue Gun](#)  
[Coverite Iron](#)  
[Calibrating thermometers](#)  
[Invisible Gloves](#)  
[Rib Stitching Needles](#)  
[Paint Strainer Cones](#)  
[Round Rib Lacing Cord](#)  
[C-102A System I Covering Manual](#)