



COVERING MATERIALS

STEARMAN PT-17 & WACO UPF

SYSTEM I

Quantity		Part Number	Description
65	Yd	SF102	2.7 oz Certified Fabric
2	Gal.	U500-01	Urethane Adhesive
3	Gal	SF-MEK	Methyl Ethyl Ketone
3	Gal	Superwash	Fabric Cleaner
9	Rolls	SF102-2P	2" Pinked Edge Surface Tape
2	Rolls	SF102-3P	3" Pinked Edge Surface Tape
2	Rolls	SF102-3PB	3" Pinked Edge Bias Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
4	Rolls	SF-REINF 3/8"	3/8" Anti Chafe/Reinforcement Tape
40	Ea	09-19200	Inspection Rings
20	Ea	09-19300	Inspection Plates
1	Pkg	L274	Drain Grommets
1	Roll	SF694-500	Flat Rib Lacing Cord
2	5Gal	300-5	Dacproofer
2	5Gal	132-5	Retarding Thinner
3	5Gal	125-5	Clear Butyrate
3	5Gal	131-5	Thinner
2	5Gal	301-5	SpraFil
2	5Gal	131-5	Thinner
20	Gal	Tinted Butyrate	Butyrate Topcoat
2	5Gal	132-5	Retarding Thinner

optional materials:

[Pre-shrunk Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Rib Stitching Needles](#)
[Paint Strainer Cones](#)
[Round Rib Lacing Cord](#)
[C-102A System I Covering Manual](#)