



## COVERING MATERIALS

AERONCA 7AC, 11AC

SYSTEM VI

Quantity		Part Number	Description
45	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
1	Qt.	U500-04	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
2	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
30	Ea.	09-19200	Inspection Rings
30	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
2	Gal.	SF6500-01	Fabric Primer Base
16	Pt.	SF6600-08	Fabric Primer Catalyst
8	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
3	Gal.	Superthane	System VI Urethane Topcoat
6	Pt.	SF6950-08	Topcoat Catalyst
2	Qt.	SF10-04	Epoxy Primer
1	Qt.	SF320-04	Epoxy Primer Catalyst

### optional materials:

Pre-shrunk Fabric tapes  
KA25B25 Gluemaster Glue Gun  
Coverite Iron  
Calibrating thermometers  
Invisible Gloves  
Rib Stitching Needles  
Viscosity Cups  
Paint Strainer Cones  
Round Rib Lacing Cord  
Tyvek Paint Suit  
D-102 System VI Covering Manual