



## COVERING MATERIALS

### AMERICAN CHAMPION 7KCAB & 8GCBC

#### SYSTEM VI

Quantity		Part Number	Description
45	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
1	Qt.	U500-04	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2S	2" Straight Edge Surface Tape
1	Roll	SF102-3S	3" Straight Edge Surface Tape
2	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
30	Ea.	09-19200	Inspection Rings
30	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
2	Gal.	SF6500-01	Fabric Primer Base
16	Pt.	SF6600-08	Fabric Primer Catalyst
8	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
3	Gal.	Superthane	System VI Urethane Topcoat
6	Pt.	SF6950-08	Topcoat Catalyst
2	Qt.	SF10-04	Epoxy Primer
1	Qt.	SF320-04	Epoxy Primer Catalyst

#### optional materials:

[Pre-shrunk Fabric tapes](#)  
[Pinked Edge Tapes](#)  
[Bias Cut Tapes](#)  
[KA25B25 Gluemaster Glue Gun](#)  
[Coverite Iron](#)  
[Calibrating thermometers](#)  
[Invisible Gloves](#)  
[Rib Stitching Needles](#)  
[Viscosity Cups](#)  
[Paint Strainer Cones](#)  
[Round Rib Lacing Cord](#)  
[Seaplane Grommets](#)  
[Tyvek Paint Suit](#)  
[D-102 System VI Covering Manual](#)