



COVERING MATERIALS

DECATHALON & CITABRIA

SYSTEM VI

Quantity		Part Number	Description
45	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
1	Qt.	U500-04	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2S	2" Straight Edge Surface Tape
1	Roll	SF102-3S	3" Straight Edge Surface Tape
1	Roll	SF102-4S	4" Straight Edge Surface Tape
2	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
30	Ea.	09-19200	Inspection Rings
30	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
2	Pkg.	AD44ABS-LF	Citabria Pop Rivets (100/pkg)
2	Gal.	SF6500-01	Fabric Primer Base
16	Pt.	SF6600-08	Fabric Primer Catalyst
8	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
3	Gal.	Superthane	System VI Urethane Topcoat
6	Pt.	SF6950-08	Topcoat Catalyst
2	Qt.	SF10-04	Epoxy Primer
1	Qt.	SF320-04	Epoxy Primer Catalyst

optional materials:

[Pre-shrunk Fabric tapes](#)
[Pinked Edge Tapes](#)
[Bias Cut Tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Rib Stitching Needles](#)
[Viscosity Cups](#)
[Paint Strainer Cones](#)
[Round Rib Lacing Cord](#)
[Seaplane Grommets](#)
[Tyvek Paint Suit](#)
[D-102 System VI Covering Manual](#)

