



COVERING MATERIALS

AVID FLYER

SYSTEM VI

Quantity		Part Number	Description
38	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
3	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
15	Ea.	09-19200	Inspection Rings
15	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
1	Gal.	SF6500-01	Fabric Primer Base
1	Qt.	SF6500-04	Fabric Primer Base
10	Pt.	SF6600-08	Fabric Primer Catalyst
5	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
2	Gal.	Superthane	System VI Urethane Topcoat
4	Pt.	SF6950-08	Topcoat Catalyst

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Rib Stitching Needles
Viscosity Cups
Paint Strainer Cones
Round Rib Lacing Cord
Tyvek Paint Suit
D-102 System VI Covering Manual