



## COVERING MATERIALS

### CAPELLA XS OR XLS

#### SYSTEM VI

Quantity		Part Number	Description
22	Yd.	SF104A	1.7 oz. Lightweight Fabric
2	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
4	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-2PB	2" Pinked Bias Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
1	Roll	SF-REINF 1/4"	1/4" Reinforcement/Anti Chafe Tape
16	Ea.	09-19200	Inspection Rings
16	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
1	Roll	SF694-500	Flat Rib Lacing Cord
1	Roll	SF-Twill-1/4"	1/4" Twill Tape
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
1	Gal.	SF6820-01	Primer & Paint Reducer
1	Gal.	Superthane	System VI Urethane Topcoat
2	Qt.	Superthane	System VI Urethane Topcoat
3	Pt.	SF6950-08	Topcoat Catalyst
2	Qt.	SF10-04	Epoxy Primer
1	Qt.	SF320-04	Epoxy Primer Catalyst

#### optional materials:

[Pour-It Lids](#)  
[Pre-shrunk Fabric tapes](#)  
[KA25B25 Gluemaster Blue Gun](#)  
[Coverite Iron](#)  
[Calibrating thermometers](#)  
[Invisible Gloves](#)  
[Rib Stitching Needles](#)  
[Viscosity Cups](#)  
[Paint Strainer Cones](#)  
[Round Rib Lacing Cord](#)  
[Tyvek Paint Suit](#)  
[D-102 System VI Covering Manual](#)

