



COVERING MATERIALS

CESSNA 120, 140, 170

SYSTEM VI

Quantity		Part Number	Description
23	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
3	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
1	Pkg.	L274	Drain Grommets
15	Ea.	09-19200	Inspection Rings
15	Ea.	09-19300	Inspection Plates
1	Gal.	SF10-01	Epoxy Metal Primer
2	Qt.	SF320-04	Epoxy Metal Primer Catalyst
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
3	Gal.	SF6820-01	Primer & Paint Reducer
4	Gal.	Superthane	System VI Urethane Topcoat
8	Pt.	SF6950-08	Topcoat Catalyst

optional materials:

[Pour-It Lids](#)
[Pre-shrunk Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Rib Stitching Needles](#)
[Viscosity Cups](#)
[Paint Strainer Cones](#)
[Round Rib Lacing Cord](#)
[Tyvek Paint Suit](#)
[D-102 System VI Covering Manual](#)