



## COVERING MATERIALS

### COMMAND-AIRE

#### SYSTEM VI

Quantity		Part Number	Description
55	Yd.	SF104A	1.7 oz. Lightweight Fabric
1	Gal.	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2P	2" Pinked Edge Surface Tape
2	Roll	SF102-2PB	2" Pinked Edge Bias Tape
2	Roll	SF-REINF 3/8"	3/8" Reinforcement/Anti Chafe Tape
16	Ea	09-19200	Inspection Rings
16	Ea	09-19300	Inspection Plates
1	Pkg	L274	Drain Grommets
7	Pkg.	AD42ABS-LF	Pop Rivets
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
2	Gal.	Superthane	System VI Urethane Topcoat
4	Pt.	SF6950-08	Topcoat Catalyst

#### optional materials:

[Pour-It Lids](#)  
[Lightweight Fabric tapes](#)  
[KA25B25 Gluemaster Glue Gun](#)  
[Coverite Iron](#)  
[Calibrating thermometers](#)  
[Invisible Gloves](#)  
[Viscosity Cups](#)  
[Paint Strainer Cones](#)  
[Round Rib Lacing Cord](#)  
[Tyvek Paint Suit](#)  
[D-102 System VI Covering Manual](#)