



## COVERING MATERIALS

### ERCOUPE

#### SYSTEM VI

Quantity		Part Number	Description
16	Yd.	SF102	2.7 oz. Certified Fabric
2	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
2	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
1	Roll	SF102-4PB	4" Pinked Edge Bias Tape
1	Roll	SF-REINF 3/8"	3/8" Reinforcement/Anti Chafe Tape
32	Ea.	09-19200	Inspection Rings
16	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
1	Gal.	SF10-01	Epoxy Metal Primer
2	Qt.	SF320-04	Epoxy Metal Primer Catalyst
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
2	Gal.	Superthane	System VI Urethane Topcoat
4	Pt.	SF6950-08	Topcoat Catalyst

#### optional materials:

[Pre-shrunk Fabric tapes](#)  
[KA25B25 Gluemaster Glue Gun](#)  
[Coverite Iron](#)  
[Calibrating thermometers](#)  
[Invisible Gloves](#)  
[Viscosity Cups](#)  
[Paint Strainer Cones](#)  
[Tyvek Paint Suit](#)  
[D-102 System VI Covering Manual](#)