



## COVERING MATERIALS

### EXCALIBUR

#### SYSTEM VI

Quantity		Part Number	Description
1	Gal.	Superwash	Fabric Cleaner
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
2	Gal.	Superthane	System VI Urethane Topcoat
4	Pt.	SF6950-08	Topcoat Catalyst

#### optional materials:

Pre-shrunk Fabric tapes  
KA25B25 Gluemaster Glue Gun  
Coverite Iron  
Calibrating thermometers  
Invisible Gloves  
Viscosity Cups  
Paint Strainer Cones  
Tyvek Paint Suit  
D-102 System VI Covering Manual