



COVERING MATERIALS

NORTH AMERICAN T-6 & NAVY SNJ

SYSTEM VI

Quantity		Part Number	Description
9	Yd.	SF102	2.7 oz. Certified Fabric
1	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
1	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
1	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
3	Gal.	SF10-01	Epoxy Metal Primer
6	Qt.	SF320-04	Epoxy Metal Primer Catalyst
2	Qt.	SF6500-04	Fabric Primer Base
4	Pt.	SF6600-08	Fabric Primer Catalyst
2	Pt.	SF6700-08	Fabric Primer Flex Agent
3	Gal.	SF6820-01	Primer & Paint Reducer
8	Gal.	Superthane	System VI Urethane Topcoat
16	Pt.	SF6950-08	Topcoat Catalyst

optional materials:

[Pre-shrunk Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Viscosity Cups](#)
[Paint Strainer Cones](#)
[Tyvek Paint Suit](#)
[D-102 System VI Covering Manual](#)