



## COVERING MATERIALS

### RHINO SYSTEM VI

Quantity		Part Number	Description
22	Yd.	SF104A	1.7 oz. Lightweight Fabric
2	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
4	Rolls	SF102-15S	1-1/2" Straight Edge Surface Tape
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
1	Gal.	SF6820-01	Primer & Paint Reducer
1	Gal.	Superthane	System VI Urethane Topcoat
2	Pt.	SF6950-08	Topcoat Catalyst

#### optional materials:

[Pour-It Lids](#)  
[Lightweight Fabric tapes](#)  
[KA25B25 Gluemaster Glue Gun](#)  
[Coverite Iron](#)  
[Calibrating thermometers](#)  
[Invisible Gloves](#)  
[Viscosity Cups](#)  
[Paint Strainer Cones](#)  
[Round Rib Lacing Cord](#)  
[Tyvek Paint Suit](#)  
[D-102 System VI Covering Manual](#)