



## COVERING MATERIALS

### R-80 TIGER MOTH

#### SYSTEM VI

Quantity		Part Number	Description
40	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal.	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2P	2" Pinked Edge Surface Tape
2	Roll	SF102-4P	4" Pinked Edge Surface Tape
1	Roll	SF-REINF 1/4"	1/4" Reinforcement/Anti Chafe Tape
26	Ea	09-19200	Inspection Rings
26	Ea	09-19300	Inspection Plates
1	Pkg	L274	Drain Grommets
1	Roll	SF694-500	Flat Rib Lacing Cord
2	Qt.	SF10-04	Epoxy Metal Primer
1	Qt.	SF320-04	Epoxy Metal Primer Catalyst
2	Gal.	SF6500-01	Fabric Primer Base
16	Pt.	SF6600-08	Fabric Primer Catalyst
8	Pt.	SF6700-08	Fabric Primer Flex Agent
2	Gal.	SF6820-01	Primer & Paint Reducer
3	Gal.	Superthane	System VI Urethane Topcoat
6	Pt.	SF6950-08	Topcoat Catalyst

#### optional materials:

[Pre-shrunk Fabric tapes](#)  
[KA25B25 Gluemaster Glue Gun](#)  
[Coverite Iron](#)  
[Calibrating thermometers](#)  
[Invisible Gloves](#)  
[Viscosity Cups](#)  
[Paint Strainer Cones](#)  
[Tyvek Paint Suit](#)  
[D-102 System VI Covering Manual](#)