



COVERING MATERIALS

PITTS S-1C & S-2A

SYSTEM I

Quantity		Part Number	Description
25	Yd.	SF102	2.7 oz. Certified Fabric
1	Gal	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
4	Roll	SF102-2S	2" Straight Edge Surface Tape
1	Roll	SF102-3S	3" Straight Edge Surface Tape
1	Roll	SF-REINF 1/4"	1/4" Reinforcement/Anti Chafe Tape
1	Roll	SF-REINF 1/2"	1/2" Reinforcement/Anti Chafe Tape
20	Ea.	09-19200	Inspection Rings
10	Ea.	09-19300	Inspection Plates
1	Pkg.	L274	Drain Grommets
1	Roll	SF694-500	Flat Rib Lacing Cord
2	Qt.	SF10-04	Epoxy Metal Primer
1	Qt.	SF320-04	Epoxy Metal Primer Catalyst
1	Qt.	Superthane	Urethane Topcoat for Metal
1	Pt.	SF6950-08	Urethane Topcoat Catalyst
3	Gal	300-1	Dacproofer
3	Gal	132-1	Retarding Thinner
1	5Gal	125-5	Clear Butyrate
1	5Gal	131-5	Thinner
1	5Gal	301-5	SpraFil
1	5Gal	131-5	Thinner
7	Gal	Tinted Butyrate	Butyrate Topcoat
3	Gal	132-1	Retarding Thinner

optional materials:

[Pre-shrunk Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Rib Stitching Needles](#)
[Paint Strainer Cones](#)
[Round Rib Lacing Cord](#)
[C-102A System I Covering Manual](#)