



COVERING MATERIALS

CGS HAWK

SYSTEM I

Quantity		Part Number	Description
35	Yd.	SF104A	1.7 oz Lightweight Fabric
2	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
3	Roll	SF102-2P	2" Pinked Edge Surface Tape
2	Roll	SF102-2PB	2" Pinked Edge Bias Tape
1	Roll	SF-REINF 3/8"	3/8" Reinforcement/Anti Chafe Tape
8	Ea.	09-19200	Inspection Rings
4	Ea.	09-19300	Inspection Plates
2	Qt.	SF10-04	Epoxy Metal Primer
1	Qt.	SF320-04	Epoxy Metal Primer Catalyst
1	Qt.	Superthane	Urethane Topcoat for Metal
1	Pt.	SF6950-08	Urethane Topcoat Catalyst
4	Gal	300-1	Dacproofer
4	Gal	132-1	Retarding Thinner
1	5Gal	125-5	Clear Butyrate
3	Gal	125-1	Clear Butyrate
1	5Gal	131-5	Thinner
3	Gal	131-1	Thinner
1	5Gal	301-5	SpraFil
3	Gal.	301-1	SpraFil
1	5Gal	131-5	Thinner
3	Gal	131-1	Thinner
10	Gal	Tinted Butyrate	Butyrate Topcoat
1	5Gal	132-5	Retarding Thinner

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Rib Stitching Needles
Paint Strainer Cones
Round Rib Lacing Cord
C-102A System I Covering Manual