



COVERING MATERIALS

DAKOTA HAWK & YOUNGSTER

SYSTEM I

Quantity		Part Number	Description
32	Yd.	SF102	2.7 oz Certified Fabric
2	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
5	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF-REINF 1/4"	1/4" Anti Chafe/Reinforcement Tape
1	Pkg	L274	Drain Grommets
20	Ea	09-19200	Inspection Rings
10	Ea	09-19300	Inspection Plates
1	Roll	SF694-500	Flat Rib Lacing Cord
4	Gal	300-1	Dacproofer
4	Gal	132-1	Retarding Thinner
1	5Gal	125-5	Clear Butyrate
1	Gal	125-1	Clear Butyrate
1	5Gal	131-5	Thinner
1	Gal	131-1	Thinner
1	5Gal	301-5	SpraFil
1	Gal	301-1	SpraFil
1	5Gal	131-5	Thinner
1	Gal	131-1	Thinner
9	Gal	Tinted Butyrate	Butyrate Topcoat
1	5Gal	132-5	Retarding Thinner

optional materials:

[Pre-shrunk Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Rib Stitching Needles](#)
[Paint Strainer Cones](#)
[Round Rib Lacing Cord](#)
[C-102A System I Covering Manual](#)