



## COVERING MATERIALS

### R-80 TIGER MOTH

#### SYSTEM I

| Quantity |      | Part Number     | Description                        |
|----------|------|-----------------|------------------------------------|
| 40       | Yd.  | SF102           | 2.7 oz Certified Fabric            |
| 1        | Gal  | U500-01         | Urethane Adhesive                  |
| 2        | Gal. | SF-MEK          | Methyl Ethyl Ketone                |
| 2        | Gal. | Superwash       | Fabric Cleaner                     |
| 5        | Roll | SF102-2P        | 2" Pinked Edge Surface Tape        |
| 1        | Roll | SF102-4P        | 4" Pinked Edge Surface Tape        |
| 1        | Roll | SF-REINF 1/4"   | 1/4" Anti Chafe/Reinforcement Tape |
| 1        | Pkg  | L274            | Drain Grommets                     |
| 26       | Ea   | 09-19200        | Inspection Rings                   |
| 13       | Ea   | 09-19300        | Inspection Plates                  |
| 1        | Roll | SF694-500       | Flat Rib Lacing Cord               |
| 1        | 5Gal | 300-5           | Dacproofer                         |
| 1        | 5Gal | 132-5           | Retarding Thinner                  |
| 1        | 5Gal | 125-5           | Clear Butyrate                     |
| 4        | Gal  | 125-1           | Clear Butyrate                     |
| 1        | 5Gal | 131-5           | Thinner                            |
| 4        | Gal  | 131-1           | Thinner                            |
| 1        | 5Gal | 301-5           | SpraFil                            |
| 4        | Gal  | 301-1           | SpraFil                            |
| 1        | 5Gal | 131-5           | Thinner                            |
| 4        | Gal  | 131-1           | Thinner                            |
| 10       | Gal  | Tinted Butyrate | Butyrate Topcoat                   |
| 1        | 5Gal | 132-5           | Retarding Thinner                  |

#### optional materials:

Pre-shrunk Fabric tapes  
KA25B25 Gluemaster Glue Gun  
Coverite Iron  
Calibrating thermometers  
Invisible Gloves  
Rib Stitching Needles  
Paint Strainer Cones  
Round Rib Lacing Cord  
C-102A System I Covering Manual