



COVERING MATERIALS

JUNIOR ACE AND BABY ACE

SYSTEM I

Quantity		Part Number	Description
32	Yd.	SF102	2.7 oz Certified Fabric
1	Gal	U500-01	Urethane Adhesive
2	Gal.	SF-MEK	Methyl Ethyl Ketone
2	Gal.	Superwash	Fabric Cleaner
4	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
1	Roll	SF-REINF 3/8"	3/8" Anti Chafe/Reinforcement Tape
15	Ea	09-19200	Inspection Rings
15	Ea	09-19300	Inspection Plates
1	Roll	SF694-500	Flat Rib Lacing Cord
4	Gal	300-1	Dacproofer
4	Gal	132-1	Retarding Thinner
1	5Gal	125-5	Clear Butyrate
3	Gal	125-1	Clear Butyrate
1	5Gal	131-5	Thinner
3	Gal	131-1	Thinner
1	5Gal	301-5	SpraFil
3	Gal	301-1	SpraFil
1	5Gal	131-5	Thinner
3	Gal	131-1	Thinner
8	Gal	Tinted Butyrate	Butyrate Topcoat
4	Gal	132-1	Retarding Thinner

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Rib Stitching Needles
Paint Strainer Cones
Round Rib Lacing Cord
C-102A System I Covering Manual