



COVERING MATERIALS

NORTH AMERICAN T-6 & NAVY SNJ - CONTROL SURFACES

SYSTEM I

Quantity		Part Number	Description
9	Yd	SF102	2.7 oz Certified Fabric
1	Qt.	U500-04	Urethane Adhesive
1	Gal	SF-MEK	Methyl Ethyl Ketone
1	Gal	Superwash	Fabric Cleaner
1	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF102-4P	4" Pinked Edge Surface Tape
1	Roll	SF-REINF 1/2"	1/2" Anti Chafe/Reinforcement Tape
2	Gal	300-1	Dacproofer
2	Gal	132-1	Retarding Thinner
3	Gal	125-1	Clear Butyrate
3	Gal	131-1	Thinner
3	Gal	301-1	SpraFil
3	Gal	131-1	Thinner
4	Gal	Tinted Butyrate	Butyrate Topcoat
2	Gal	132-1	Retarding Thinner

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Rib Stitching Needles
Paint Strainer Cones
Round Rib Lacing Cord
C-102A System I Covering Manual