



COVERING MATERIALS

CASSUTT 111M RACER

SYSTEM VI

Quantity		Part Number	Description
10	Yd.	SF102	2.7 oz. Certified Fabric
9	Yd.	SF104A	1.7 oz. Lightweight Fabric
2	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
3	Roll	SF102-2S	2" Straight Edge Surface Tape
1	Roll	SF102-3S	3" Straight Edge Surface Tape
2	Roll	SF-REINF 3/8"	3/8" Reinforcement/Anti Chafe Tape
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
1	Gal.	SF6820-01	Primer & Paint Reducer
2	Gal.	Superthane	System VI Urethane Topcoat
4	Pt.	SF6950-08	Topcoat Catalyst

optional materials:

[Pour-It Lids](#)
[Pre-shrunk Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Rib Stitching Needles](#)
[Viscosity Cups](#)
[Paint Strainer Cones](#)
[Round Rib Lacing Cord](#)
[Tyvek Paint Suit](#)
[D-102 System VI Covering Manual](#)