



COVERING MATERIALS

Free Bird Innovations (Fuselage)

SYSTEM VI

Quantity		Part Number	Description
1	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
1	Qt.	SF6500-04	Fabric Primer Base
2	Pt.	SF6600-08	Fabric Primer Catalyst
1	Pt.	SF6700-08	Fabric Primer Flex Agent
1	Gal.	SF6820-01	Primer & Paint Reducer
1	Qt.	Superthane	System VI Urethane Topcoat
1	Pt.	SF6950-08	Topcoat Catalyst

optional materials:

[Pour-It Lids](#)
[Lightweight Fabric tapes](#)
[KA25B25 Gluemaster Glue Gun](#)
[Coverite Iron](#)
[Calibrating thermometers](#)
[Invisible Gloves](#)
[Viscosity Cups](#)
[Paint Strainer Cones](#)
[Round Rib Lacing Cord](#)
[Tyvek Paint Suit](#)
[D-102 System VI Covering Manual](#)