



COVERING MATERIALS

MAULE - FUSELAGE & EMPENNAGE

SYSTEM VI

Quantity		Part Number	Description
28	Yd.	SF102	2.7 oz. Certified Fabric
2	Qt.	U500-04	Urethane Adhesive
1	Gal.	SF-MEK	Methyl Ethyl Ketone
1	Gal.	Superwash	Fabric Cleaner
3	Roll	SF102-2P	2" Pinked Edge Surface Tape
1	Roll	SF102-3P	3" Pinked Edge Surface Tape
1	Roll	SF-REINF 3/8"	3/8" Reinforcement/Anti Chafe Tape
1	Roll	SF694-500	Flat Rib Lacing Cord
1	Gal.	SF6500-01	Fabric Primer Base
8	Pt.	SF6600-08	Fabric Primer Catalyst
4	Pt.	SF6700-08	Fabric Primer Flex Agent
1	Gal.	SF6820-01	Primer & Paint Reducer
3	Gal.	Superthane	System VI Urethane Topcoat
6	Pt.	SF6950-08	Topcoat Catalyst
2	Gal.	SF10-01	Epoxy Metal Primer
4	Qt.	SF320-04	Epoxy Metal Primer Catalyst

optional materials:

Pre-shrunk Fabric tapes
KA25B25 Gluemaster Glue Gun
Coverite Iron
Calibrating thermometers
Invisible Gloves
Viscosity Cups
Paint Strainer Cones
Round Rib Lacing Cord
Tyvek Paint Suit
D-102 System VI Covering Manual